

Date: Friday, 7/4/2008 12:48:28 PM  
 User: Kim Johnston

## Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : BUSHING
Job Number : 40277	
Estimate Number : 10725	
P.O. Number :	Part Number : D2652
This Issue : 7/4/2008 S.O. No. :	Drawing Number : D2652 REV A
Prsht Rev. : NC	Project Number : N/A
First Issue : 1 / Type : MACHINED PARTS	Drawing Revision : A
Previous Run : 39222	Material :
Written By :	Due Date : 7/30/2008 Qty: 200 Um: Each
Checked & Approved By : <u>08 07 07</u>	
Comment : Est Rev.B 02.06.13 Now machined in house. NG	

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M303R0500	303 Round Bar 0.500"
-----	-----------	----------------------



Comment: Qty.: 0.0578 f(s)/Unit Total: 11.5500 f(s)

Material: 303 ss .500" Round Bar

(M303R0500)

Batch: m106996mme 08/07/11

(94)

2.0	HARDINGE	HARDINGE CNC LATHE SMALL
-----	----------	--------------------------



Comment: 1-TURN AS PER FOLIO FA250 &amp; DWG D2652

FOLIO REV: ADWG REV: A

2-DEBURR AS REQUIRED

mme 08/07/11

(94)

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

mme 08/07/11

(94)

4.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

mme 08/07/11

(94)

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: 398/1/11

(V94)

SP

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Friday, 7/4/2008 12:48:28 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 40277

Part Number: D2652

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



08/07/16 *[Signature]*

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



mf 08-07-15

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries








DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2652	REV. A SHEET 1 OF 1
DATE 97:03:25		TITLE BUSHING	SCALE 1:1

RELEASED  
97/04/25 DS



SHOP COPY  
RETURN TO  
ENGINEERING  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
WORK ORDER  
NO. 40277

MATERIAL: AISI 303 SS  
NOTE: BREAK ALL SHARP CORNERS 0.010 MAX  
TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED